


FIGURE 1



[illegible]

19	19
1915	1915

FIGURE 3A




FIGURE 3B




FIGURE 3C





FIGURE 1






FIGURE 5

18, 12

FIGURE 6




FIGURE 7




FIGURE 8A




FIGURE 8B




FIGURE 8C




FIGURE 8D




FIGURE 9





FIGURE 10




[illegible]

FIGURE 12




FIGURE 13

FIGURE 13




FIGURE 14a




FIGURE 14b






FIGURE 166a




Improper Placement:
Incomplete Ablation
of Tumor Volume

FIGURE 166b




Improper Placement:
Insufficient Healthy
Tissue Margin

FIGURE 166c




Proper Placement

FIGURE 17a



Detection of Incomplete Ablation
Via rotation of electrode/sensor array

FIGURE 17b



Detection of Incomplete Ablation by
Deployment of passive Resonant members (18)
of Sensing members (22m)

FIGURE 18a




FIGURE 18b




FIGURE 19




FIGURE 20




FIGURE 21a




FIGURE 21b




FIGURE 21c




FIGURE 21d






FIGURE 21e

FIGURE 21f





FIGURE 22




FIGURE 23




FIGURE 24




FIGURE 25




FIGURE 26




FIGURE 27






FIGURE 28

FIGURE 29






FIGURE 30

